

Oxy cutting Flame adjust

Find the right oxy cutting flames

Task: The oxy cutting process is not correct. The heating time is too long, the piercing generates splash and the cutting image is not OK.

Solution: It is important to set the correct flame.
Look at: https://youtu.be/uoN4dT_sOM
And ask service@iht-automation.com for cutting table

Function:

